



UP DOWN 1 2 3 4 5 6 7 8 9 10 DOWN

TUBE TESTER

TUBE	SHUNT	FIL	SEL	UP	DOWN	TUBE	SHUNT	FIL	SEL	UP	DOWN
6X4	25	6.3	1	1.5	1.5	6X4	25	6.3	1	1.5	1.5
6X5	15	6.3	1	1.4	1.4	6X5	15	6.3	1	1.4	1.4
6X6	14	6.3	1	4.5	1.6	6X6	14	6.3	1	4.5	1.6
6X7	14	6.3	1	5.4	1.6	6X7	14	6.3	1	5.4	1.6
6A1	30	6.3	1	1.2	1.2	6A1	30	6.3	1	1.2	1.2
6A2	30	6.3	1	1.2	1.2	6A2	30	6.3	1	1.2	1.2



TUBE ON
SHORT OFF

SELECTOR
SHORT CIRCUIT
WERT OVERLOAD
SER. NO. 5528-10